

# Photographic Log

**Project:**  
St Cloud NR2 Project

**Site Location:**  
St Cloud WWTF

**Project No.**  
13053

**Photo No.**  
1

**Date:**  
2018/10/29

**Direction Photo Taken**  
W

**Photo Taken By:**  
JWS

**Description:** Image is of McCormick Insulation working on jacketing duct insulation in the 500 Building.



**Photo No.**  
2

**Date:**  
2018/10/30

**Direction Photo Taken:**  
N

**Photo Taken By:**  
JWS

**Description:** Image is of the Andritz GBT dewatering WAS for the WAS P Release 910 Structure.



# Photographic Log

**Project:**  
St Cloud NR2 Project

**Site Location:**  
St Cloud WWTF

**Project No.**  
13053


**Photo No.**  
3

**Date:**  
2018/10/30

**Direction Photo Taken**  
N

**Photo Taken By:**  
JWS

**Description:** Image is of the Komline GBT co thickening the WAS P Release and primary sludge.



**Photo No.**  
4

**Date:**  
2018/11/6

**Direction Photo Taken:**  
SE

**Photo Taken By:**  
JWS

**Description:** Image is of Rice Lake working on the construction of a temporary cover for the HSW 305 Structure.



# Photographic Log

**Project:**  
St Cloud NR2 Project

**Site Location:**  
St Cloud WWTF

**Project No.**  
13053

**Photo No.**  
5

**Date:**  
2018/11/6

**Direction Photo Taken**  
W

**Photo Taken By:**  
JWS

**Description:** Image is of plant operator meeting with Lystek engineer on the operation of the Lystek Class A Biosolids Treatment Process.

